

Report To:

All Good Demolition and Asbestos Removal
2/5 Elwin Road
Raymond Terrace, NSW 2324
Asbestos Removal Licence Number: AD 212784

Attention: Mr Scott Whatley

Clearance Certification following the removal of Non-Friable Asbestos Containing Building Material:



The Site at 175 Wollombi Road Farley NSW 2320

Asbestos Clearance Inspection


Note:


The inspection was undertaken in visually accessible areas only. Asbestos Containing Materials remaining in-situ, concealed in/under adjacent areas, or that are buried at this time and may be exposed in future works do not form part of this clearance.

Removal Work Details.			
Date removal work was carried out	10 th December 2021		
Site address where removal work being undertaken:	175 Wollombi Road Farley NSW 2320		
Details of specific asbestos removal work area(s):	Exterior wall cladding and roofing from wood and chicken sheds.		
Name of Licensed Asbestos Removalist:	All Good Demolition and Asbestos Removal		
Name of Licensed Asbestos Removalist Supervisor:	Scott Whatley		
Inspection Details.			
Date of clearance inspection	Friday 10 th December 2021		
Time of clearance inspection	approximately 2:30 pm		
Asbestos Removal Work Area		YES	NO
Inspection of the specific area(s) detailed above found no remaining asbestos material from this removal		x	
Can this area(s) be reoccupied:		x	
Has any additional information been attached (e.g, photos, plans etc):		x	
Limitations: Detail of any trapped or inaccessible ACM unable to be removed at this time:			
Site specific comments:		Asbestos Containing Materials, concealed in/under adjacent areas, or that are buried at this time and may be exposed in future works do not form part of this clearance.	
Clearance Declaration		YES	NO
The removal area and surrounds are free from any visible ACM associated with this removal work:		x	
The transit and waste routes are free from any visible ACM:		x	
All asbestos in the scope of this removal works has been removed:		x	
Asbestos Removal Documentation		YES	NO
Do you have a copy, have you sighted/discussed the ARCP:			x
Do you have a copy of the notification form:			x

Post-Removal Photos:

175 Wollombi Road
Farley NSW 2320







Limitations

The visual clearance inspection conducted by Panacea Occupational Safety and Health is in accordance with the requirements specified in the Section 3:10 **Safe Work Australia Code of Practice: How to Safely Remove Asbestos 2nd Edition (Aug 2019)**, but does not guarantee the identification, location and/or removal of all Asbestos Containing Material that may be present within this specific site.

Please note: This report and the content remain the property of Panacea Occupational Safety and Health until such time as all charges relating to it have been paid in full.

Yours Faithfully
For Panacea Occupational Safety and Health

Stephen Mounty

Stephen Mounty
WorkCover Asbestos Assessor License No LAA 000168
Tel: 0490 540128